

## Cloud Construction

## Clifton Park/Bellaire ES Consolidation

Monthly Progress Report - June 2021



Certificate of Occupancy received.



Interior: Main entry and library.



Interior: Little kids playground.



Interior: Music room classroom set up.

### This Month's Major Activities:

- Interior: Responding to warranty calls.
- Interior: Certificate of Occupancy.

### Next Month's Major Activities:

- Exterior: Removal of portables to finish fencing.
- Interior: Responding to warranty calls.

Design Percent Complete - 100%

Construction Percent Complete - 94.8%