



New Campus: New campus is open and fully functional!



Exterior: Sod has been installed in front field.



Interior: Final fencing at paving is completed.



Interior: Front reception counter is ready for visitors.

This Month's Major Activities:

- Interior: Repairs on warranty calls are continuing.
- Exterior: Sod, irrigation and fencing.

Next Month's Major Activities:

- Interior: Immediate response to all warranty calls.
- Exterior: Final inspections.